





Technical requirements

1. After the components of the fan are assembled, there is no abnormal sound during high-speed operation;
2. The impeller parts are running at 2 times high speed (2200rpm), and there is no loosening after 8 hours:
3. The dimensional tolerance of the unmarked is according to the accuracy requirements of CB/T1804-2000-C level.

No.	Item	Material	Qty
1	Impeller	Galvanized sheet	
2	Casing	Galvanized sheet	

					Stage Mark						
					S				Material	Galvanized sheet	Ratio
					Version	A1	Name	Date	Ningbo Longwell Electric Technology Co., Limited		
					Design		GUO	20260804	LWFC-145*190-03		
					Audit						
					Technical						
					Standard						
Mark	Qty	Sign	Name	Date	Approve				1	1	